


## CASE STUDY: K-MotorShield Motor Covers

|                           |                                   |
|---------------------------|-----------------------------------|
| Kinder Australia Product: | <b>K-MotorShield Motor Covers</b> |
| Product category:         | Safety & Environmental            |
| Location:                 | Boyer Paper Mill, Boyer, Tasmania |
| Material application:     | Pulp                              |
| Installation date:        | October 2010                      |
| Number installed:         | 25                                |

### Previous problem:



Set in a laboratory, photo example of pulp clogging the motor



Photo of Boyer Paper Mill, Tasmania

Our customer is responsible for the supply of approx 600,000 tonnes of paper to publishers and commercial printers throughout Australia. The paper mill at Boyer uses 100% plantation softwood to produce about 40% of the paper used in Australian news print production as well as exports.

The mill operates with a focus on innovation in logistics and service systems, underpinning supply capabilities with an emphasis on sustainability, including waste management.

*"In the past we used a customised metal covering to try and prevent the pulp building up on our motors, which in turn would reduce airflow over the cooling fins and resulted in our bearing temperatures increasing significantly. When one of our motors overheats it needs to be rewound twice as frequently as a clean motor with free airflow. It was a necessary but inefficient manpower issue."*

*As well as these constant maintenance stoppages, the metal covers would need washing down regularly and so would rust and need replacing on an on-going basis. They were becoming a costly option to replace."*



<https://kinder.com.au>

Subject to © Kinder Australia Pty Ltd  
Issue: 202102

### Kinder Australia Pty Ltd

26 Canterbury Road, Braeside VIC 3195  
PO Box 1026, Braeside VIC 3195

☎ +61 3 8587 9111  
📠 +61 3 8587 9101

✉ conveyorsolutions@kinder.com.au  
ABN: 28 006 489 238

## CASE STUDY: K-MotorShield Motor Covers

### Resolution:

*"The K-MotorShield Motor Covers were surprisingly simple to install. Because they are made of fibreglass they were very lightweight and easy to manoeuvre.*

*But most importantly they do the job intended – they keep our motors pulp-free and stop our motors running hot. They are a really fantastic low-maintenance and long-term return on investment product.*

*Our motors are located outside, so they have to withstand some harsh weather but so far they are a very effective shield and we are going to look at how we can install them on other problem locations at the mill."*



Photo example of K-MotorShield on site at a paper mill protecting the electric motor



<https://kinder.com.au>

Subject to © Kinder Australia Pty Ltd  
Issue: 202102

### Kinder Australia Pty Ltd

26 Canterbury Road, Braeside VIC 3195  
PO Box 1026, Braeside VIC 3195

☎ +61 3 8587 9111  
☎ +61 3 8587 9101

✉ [conveyorsolutions@kinder.com.au](mailto:conveyorsolutions@kinder.com.au)  
ABN: 28 006 489 238